


## PRDA-INDEX




DIMENSIONS AND INSTRUCTIONS	Page 1
ACCESSORIES	
PRESSURE CONVERSION TABLE	Page 2
SETTING PROCEDURE	
MANUAL SETTING MODE	Page 3
FUNCTIONS	
INSTRUCTIONS IN THE EVENT OF ERRORS	Page 4
TECHNICAL DATA	
WARNINGS	


## ELETTRIC CIRCUIT PNP



## INTERFACE PRDA




## DIMENSIONS AND WEIGHT



WEIGHT: 135g


## SETTING

1. Pressure switch series PRDA has No. 2 input for pressure, select the more convenient one for the setting
2. Close not used input with the supplied plug. Use seals to prevent pressure leakages




## ACCESSORIES

### PROTECTION COVER AND PANEL MOUNTING SYSTEM SFPR




### FIXING BRACKETS STPR (PAIR)




## CHANGE PRESSURE MEASURE UNIT

When settled pressure is not in **kPa** or **MPa**, put the measure unit label in the front panel, in the area indicated in the picture, to be sure that pressure unit is not wrong and that there is not setting errors




	TO	Pa	kPa	Mpa	kgf/cm2	mmHg	psi	bar	InHg
<b>FROM</b>									
1 Pa		1	0,001	0,000001	0,000010197	0,00750062	0,000145038	0,00001	0,0002593
1 kPa		1000,000	1	0,001	0,010197	7,500616	0,0145038	0,010000	0,2953
1 Mpa		1000000	1000	1	10,197	7500,616	145,038	10	295,2998
1 kgf/cm2		98066,5	98,0665	0,098067	1	735,559	14,2233	0,980665	28,95979
1 mmHg		133,32	0,13332	0,000133	0,0013595	1	0,019336	0,0013332	0,039370
1 psi		6895	6,895	0,006895	0,07031	51,7157	1	0,06895	2,036074
1 bar		100000,0	100	0,1	1,01972	750,062	14,5038	1	29,52998
1 InHg		3386,388	3,386388	0,003386	0,034530	25,40000	0,491141	0,033863	1

## SETTING PROCEDURE




## MEASURE MODE



Press SET button and hold 3 seconds

## INITIAL SETTING MODE

### 1. UNIT



Set the measure unit with the ▲ and ▼ button  
*Pa* : kPa or MPa  
*kgf/cm<sup>2</sup>*  
*bar* : bar  
*psi* : psi

Press SET button


### 2. OUT1 OUTPUT MODE



Set output mode of OUT1 with ▲ or ▼.  
 "1no" : Normally open  
 "1nc" : Normally closed

Press SET button


### 3. OUT2 OUTPUT MODE



Set output mode of OUT2 with ▲ or ▼.  
 "2no" : Normally open  
 "2nc" : Normally closed

Press SET button


### 4. RESPONSE TIME



Set the response time with ▲ or ▼ button.  
 (Select from "2.5 = 2.5ms," "24 = 2.4ms," "192 = 192 ms," and "768 = 768ms. ")

Press SET button

### 5. MANUAL / AUTO



Select the auto preset mode or manual calibration mode with ▲ or ▼ button  
 "Aut" = Auto preset mode  
 "mAn" = Manual calibration mode

Press SET button to finish

## MANUAL SETTING MODE


### 1. MANUAL SELECTION

Select manual setting mode as initial regulating mode



Press the SET button and hold it until "P\_1" or "n\_1" appears on the display.  
 The led shows P\_\* at normal open mode and n\_\* at normal close mode.

### 2. P\_1 or n\_1




Button ▲ : Increase the set point value  
 Button ▼ : Decrease the set point value  
 "P\_1" or "n\_1" and the set point value light up alternately

Press SET button


### 3. P\_2 or n\_2



Button ▲: Increase the set point value  
 Button ▼: Decrease the set point value  
 "P\_2" or "n\_2" and the set point value light up alternately



Press SET button




Button ▲: Increase the set point value  
 Button ▼: Decrease the set point value  
 "P\_3" or "n\_3" and the set point value light up alternately



Press SET button

### 5. P\_4 or n\_4



Button ▲: Increase the set point value  
 Button ▼: Decrease the set point value  
 "P\_4" or "n\_4" and the set point value light up alternately




Press SET button to finish

## AUTO SETTING MODE

### 1. AUTO SELECTION

Select auto preset mode as the initial setting mode.




Press the SET button and hold it until "RP1" appears on the display.



Press SET button

### 2. PREPARATION OF AUTO PRESET




Prepare the equipment to be set while "RP1" is displayed. If OUT1 setting is not required, press the ▼ and ▲ buttons simultaneously to skip to "RP2".




Press SET button

### 3. OUT1 AUTO PRESET




Repeat vacuum and break several times while "AIL" is displayed. The optimum set point value is determined automatically.




Press SET button

### 4. PREPARATION OF AUTO PRESET



Change the vacuum nozzle or other conditions of the work piece and supply vacuum pressure. If OUT2 setting is not required, press the ▼ and ▲ buttons simultaneously to skip to the measurement mode.



Press SET button

### 5. OUT2 AUTO PRESET




Repeat vacuum and break several times while "A2L" is displayed. The optimum set point value is determined automatically.



Press SET button to finish

## FUNCTIONS


### SETTING ZERO POINT




This function uses the measured pressure at the moment of auto shift input as refering pressure and adjusts regulating point values "P\_1" and "P\_2" of the output sensor 1 and "P\_3" and "P\_4" of the output sensor 2. Pressure detection is not influenced by fluctuations of primary pressure. Set zero point with atmospheric pressure. Hold pressed both ▲ and ▼ buttons simultaneously to reset the display. After resetting the operation returns to the measurement mode automatically.

### KEY LOCK

This function avoids that buttons could be unintentionally pressed



Press SET button for at least 2 seconds release when the display turns to "UnL".




Change the displays to "LoC" with ▲ or ▼ buttons




Press SET button to finish

### SETTING PEAK/BOTTOM VALUES




Press the button ▲ at least for 2 second during pressure display to enter the peak display mode. The displayed value will blink. To return, press the ▲ button again at least for 2 second.




Press the button ▼ at least for 1 second during pressure display to enter the bottom display mode. The displayed value will blink. To return, press the ▼ button again at least for 1 second.

### KEY RELEASE



Press the SET button at least 4 seconds. Release it when the display turns to "UnL".



Change the display to "UnL" with the ▲ or ▼ button.



Press SET button to finish






## INSTRUCTIONS IN THE EVENT OF ERRORS

ERROR DESCRIPTION		DISPLAY LCD	DESCRIPTION	SOLUTIONS
Over current error	OUT 1	Er1	Load current of switch output is > 80mA.	1) Shut off the power supply. After eliminating the factor that caused the over current 2) Reduce the load under than 80mA
	OUT 2	Er2		
Residual pressure		Er3	During the setting of zero point, the environment pressure is $\geq \pm 0,03$ Mpa.	Bring the input pressure back to atmospheric pressure and try using the zero out function.
Applied pressure error		---	Supply pressure exceeds the maximum regulating pressure.	Reduce/Increase supply pressure to within the regulating pressure range.
		----	Supply pressure is below the minimum regulating pressure.	
Auto shift error		Er4	Internal data error	Shut off the instrument and restart up. If the switch does not come back to a normal operation, please contact Waircom-MBS S.p.A. for an inspection
		Er6	Internal data error	
		Er7	Internal data error	
		Er8	Internal data error	

## TECHNICAL DATA

Rated pressure range		0÷10 bar
Setting pressure range		-1÷10 bar
Capacity pressure		15 bar
Fluid		Air-not corrosive and incombustible gases
Pressure setting resolution	kPa	-
	MPa	0.001
	Kg/cm <sup>2</sup>	0.01
	bar	0.1
	psi	0.1
	mmHG	-
inHG		-
Power supply voltage		12÷24VDC $\pm 10\%$ , ripple (p-p) $\leq 10\%$
Sensor output		PNP 2 output (max applied voltage 24V max load current 80mA)
Repeatability		$\pm 0.2\%$ F.S. $\pm$ max. 1 digit
Hysteresis	Hysteresis mode	Variable ( $\geq 0$ )
	Comparator mode	Fix (3 digit)
Response time		$\leq 2.5$ ms (with chattering prevention function: 24ms, 192ms e 768ms selected)
Short -circuit protection		Yes
Resolution display		3 ½ a digit display 7 segments (sampling frequency 5Hz)
Accuracy display		$\pm 2\%$ F.S. $\pm$ Max 1 digit (con Temperature of ambient: $25 \pm 3^\circ\text{C}$ )
Optical indicator		OUT1= GREEN LED that lights up when ON OUT2= RED LED that lights up when ON
Analog output		Output voltage: $1\div 5V \pm 2.5\%$ F.S.
Environmental resistance	Protection	IP50 (special version IP65)
	Working temperature	Operating: $0\div 50^\circ\text{C}$ ; Stored: $-10\div 60^\circ\text{C}$ (With no condensation or freezing)
	C. humidity	Operating and stored: $35 \div 85\%$ RH (With no condensation)
	Withstand voltage	1000Vca for 1 min, between wires and body
	Insulation resistance	$\geq 50\text{M}\Omega$ ( at 500Vcc) between wires and body
	Vibration resistance	$10\div 55\text{Hz}$ with 1.5mm amplitude or $98\text{m/s}^2$ , the smaller
Shock resistance		$980\text{ m/s}^2$ in X, Y, Z directions 3 times each (Not energized)
Temperature characteristics		$\leq \pm 2.5\%$ F.S. or less of measured pressure at $25^\circ\text{C}$ in temperature range of 0 to $50^\circ\text{C}$

## WARNINGS

- |   |  |
|---|--|
|  <p><b>MACHINERY</b></p> <ol style="list-style-type: none"> <li>Be sure that there is not voltage in the machinery before to do the electrical connection</li> <li>Do not exceed the maximum allowed load (80mA)</li> <li>Operate the sensor only with the indicated voltage</li> <li>Power supply voltage has to be stabilized. The correct working of the instrument can be disturbed by the presence of large magnetic fields near it.</li> <li>Operate the switch within the regulating pressure range and without exceeding the max operating pressure</li> </ol> |  <p><b>WIRING</b></p> <ol style="list-style-type: none"> <li>Verify the colours and numbers of wires</li> <li>Avoid to repeatability stretch and bend the wires</li> <li>Verify that there is no faulty wiring insulation (contact with the other circuits, ground fault, Improper insulation between wires, etc).</li> </ol> |
|  <p><b>MOUNTING</b></p> <ol style="list-style-type: none"> <li>If the instrument is not operating properly, do not continue to use it</li> <li>Mount the instrument using the proper tightening couple</li> </ol>  |  <p><b>MAINTENANCE</b></p> <ol style="list-style-type: none"> <li>Perform periodic inspections to ensure proper operating of the instrument</li> <li>Take precautions using a switch for an interlock circuit</li> </ol>  |
|  <p><b>ENVIRONMENT</b></p> <ol style="list-style-type: none"> <li>Never use in the presence of explosive gases</li> <li>Never use in environment exposed to welding liquid, oils and solvents</li> </ol>   |  |